

*The Basic Guide to*  
**Mold Awareness**  
**- Online Learning Course -**

---

**SAMPLE LABORATORY REPORT 4**

**Non-Viable laboratory report for a typical home**    **Environmental Microbiology Laboratory, Inc.**  
1800 Sullivan Ave., Suite 209, Daly City, CA 94015  
(650) 991-3436 Fax (650) 991-2243 [www.emlab.com](http://www.emlab.com)

Client: GHH Engineering, Inc.  
C/O: Ms. Jennifer Bailey  
Re:

Date of Sampling: 7-21-2000  
Date of Receipt: 7-25-2000  
Date of Report: 08-03-2000

**SWAB SAMPLES: FUNGAL CULTURE**

**Swab sample #51: West bed framing**

Quantity	Fungi isolated (Cellulose, DG18, MEA)
<100cfu/swab	No growth

**Swab Sample #51: South bathroom framing**

Quantity	Fungi isolated (Cellulose, DG18, MEA)
<100cfu/swab	No growth

**Swab sample #51: Curtain**

Quantity	Fungi insolated (Cellulose, DG18, MEA)
60,000 cfu/swab	Yeasts, <i>Rhodotorula</i> species
17,000 cfu/swab	<i>Cladosporium</i> species
7,000 cfu/swab	<i>Ulocladium</i> species
2,000 cfu/swab	<i>Alternaria</i> species
2,000 cfu/swab	<i>Aspergillus niger</i>

**Swab sample #47: Living room window**

<b>Quantity</b>	<b>Fungi isolated (Cellulose, DG18, MEA)</b>
300 cfu/swab	<i>Chaetomium</i> species

[Previous Page](#) - [Home Page](#) - [Table of Contents](#) - [Next Page](#)

---

This site is owned and maintained by the [Environmental Assessment Association](#).  
Send comments, errors, suggestions to [Webmaster](#).

Last revised: .

Copyright © 2001 [GHH Engineering, Inc.] All rights reserved. No part of this may be reproduced in any form, electronic or mechanical, including photocopying, recording, or any other information storage and retrieval system, without written permission from GHH Engineering, Inc.